



Photo Documentation Copsa Mica Site Visit in the Carbosim Area

icpdr **iksd**
International
Commission
for the Protection
of the Danube River
Internationale
Kommission
zum Schutz
der Donau



View Northbound to the Industrial Area of Copsa Mica



in the

Umwelt
Bundes
Amt 
für Mensch und Umwelt





Photos 1 and 2: View from the Bridge in Direction to the Carbosim Area



Photo 3: Plexiglas Production Line



Photo 4: Former Location of Transformers



Photo 5: Soil Contamination in the Southeast of the Carbosim Area -1



Photo 6: Soil Contamination in the Southeast of the Carbosim Area -2



Photo 7: Contaminated Water in Storage Basin



Photo 8: Unsecured Area in the Southeast of the Carbosim Area



**Photo 9: Improper Deconstruction of
Production Facilities**



Photo 10: View Southbound



Photo 11: Soil Contamination nearby Storage Tanks



Photo 12: Improper Disposal of Industrial Residues



Foto 13: Pipeline



**Foto 14: Ruins of the Carbon Black
Fabrication**



Photo 15: Soil and Water Contamination by Improper Disposal



Photo 16: Improper Disposal at the Carbosim Area



Photo 17: Soil Contamination by Oil and Tar Components - 1



Photo 18: Soil Contamination by Oil and Tar Components - 2



**Photo 21: View to the North East from
the Carbosim Area**



**Photo 22: Former Ammonia Storage
Facilities at the Carbosim Area - 1**



Photo 23: Derelict Ammonia Storage Facilities at the Carbosim Area - 2



Photo 24: Derelict Ammonia Storage Facilities at the Carbosim Area – 3



Photo 25: Visit of the Former Fabrication Hall in Carbosim - 1



Photo 26: Visit of the Former Fabrication Hall in Carbosim - 2



Photo 27: Visit of the Former Fabrication Hall in Carbosim - 3



Photo 28: Visit of the Former Fabrication Hall in Carbosim - 4



Photo Documentation Copsa Mica Site Visit in the Sometra Area

icpdr **iksd**
International
Commission
for the Protection
of the Danube River
Internationale
Kommission
zum Schutz
der Donau




View Westbound to the Industrial Area of Copsa Mica



in the

Umwelt
Bundes
Amt 
für Mensch und Umwelt





Photos 1 and 2: Overview of the Production Line of the Sometra Factory



Photo 3: Site Visit at Sometra – 1



Photo 4: Site Visit at Sometra - 2



**Photo 5: Waste Disposal at the Factory Site
next to the Cooling Tower - 1**



**Photo 6: Waste Disposal at the Factory Site
next to the Cooling Tower - 2**



Photo 7: Disposal of Industrial Residues and Slag Dumps in the Background -1



Photo 8: Disposal of Industrial Residues and Slag Dumps in the Background -2



**Photo 9: View from the Top of
the Slag Dump - 1**



**Photo 10: View from the Top of
the Slag Dump - 2**



Photo 11: Rain Water will wash Slope Material directly into Tarnava River



Photo 12: View to the Tarnava River – 1



Photo 13: View to the Tarnava River - 2



Photo 14: Flue Gas Scrubbing of the Ore Processing Line



**Photo 15: Ruin of an abandoned
Production Line at the Sometra
Site**



Photo 16: Inspection of the River Dam -1



Photo 17: Inspection of the River Dam -2